



Certificate of Analysis

Specification of Hydrogen Peroxide

Sr No.	Characteristics	Unit	Specifications
1	Assay	%	50% max
2	Stability		0.30 max
3	Acidity (as H ₂ SO ₄)		0.03 max
4	Iron (as Fe ⁺⁺⁺)	ppm	1.00 max
5	Copper (as Cu)	ppm	0.10 max
6	Arsenic (as As)	ppm	2.00 max
7	Lead (as Pb)	ppm	10.00 max

For any further clarification in this regards please do feel free to contact us at any point of time at info@arrowfinechemicals.com.

Assuring you great attention at all times.

For Arrow Fine Chemicals

Quality Assurance Department

** Note : This is a computer generated report hence not needed to sign.

